

Exhibit 2: Site Photos



Downstream outlets. Both culverts fail to meet passage criteria for all age classes of juvenile salmonids.

Upstream inlets are undersized and impede flow during large storm events.



Exhibit 2: Site Photos



Downstream culvert outlet. Note the turbulence and relatively high velocity that make this a total passage barrier for juvenile salmonids.